

## PCN # **734110500010210**Address: **1061 Summer wood**

ITEM

Permit Application date
Permit issued
Roof Sheathing Inspection
Roof Metal Inspection
Roof Sheathing Inspection
Roof Metal Inspection
Roof in Progress Inspection
Status Inspection

Miscellanos notes
Roof inprogress
Miscellanos notes
Miscellanos notes

Status Inspection

Meeting with Contractor
Email from Contractor
status inspection

DATE	COMMENTS/ACTIONS
January 17/2017	Remove shingle & install metal roof
January 19 2017	Permit issued to contractor
Feb 01,2017	Inspector DH/ status DA 110.5 no one on site ,work not ready for insepction
Feb 01,2017	Inspector DH/ status DA 110.5 no one on site ,work not ready for insepction
Feb 06,2017	Inspector DH approved inspection
Feb 06,2017	Inspector DH/ approved inspection
April 18,2017	Inspector DH/ status DP 107.3.1 Construction Documents not on site reinspetion fee \$50.00
June 22,2017	Owner requested status insepction roofer will not answer the home owner and has not shown up in months. Homeowner would like some clarification Inspection results 107.4 Consturction not according to approved plans - work shall be installed in accordance with the approved construction documents.
	Meet with homeowner & contractor to discuss the insepction process. 3/4 of the roof was completed metal panels were not SECURED AS PER PROI ROOF
	SOME NAILS WERE NOT REMOVED AND PROTRUDING UP INTO METAL
	PANELS.A PLUMBING ROOF VENT WAS INSTALLED IN THE V-CRIMP
	METAL PANEL.THIS VENT NEEDS TO BE RELOCATED.A NEW FLAT DECK
	WAS INSTALLED.PROVIDE PHOTOS & A AFFIDAVIT (NOTARIZED)ON
	CONTACTORS COMPANY LETTER HEAD WITH ADDRESS & PERMIT #
	STATING THE WHOLE INSTALLATION PROCESS OF THE NEW FLAT DECK.
	A ROOF IN-PROGRESS INSPECTION WILL BE REQUIRED TO VERIFY
	ROOF PANEL INSTALLATION.
August 14,2017	Permit extended to 11/14/17 pending payment of fees.
August 15,2017	Inspector TWM status DA corrections from first inspection have not been made.
Oct 16,2017	This permit not to be extended beyond 11/14/2017 unless approved by the building official. JT/MCM
November 29,2017	Called and spoke with contractor Shawn Wolfe and advised him the permit has expired and a complaint has been filed with the Construction Board of
Friday, January 5, 2018	Status inspection verified no change from 6/22/2017 except roof vent was relocated. Roof panels and ridge cap not replaced and underlayment remain
Jaunuary 8, 2018	Advised Contractor Shawn Wolfe to provide new NOA and Manufacturers letters for underlayment exposure limit and reuse of metal panels requiring
W. 1 1 2 10 2010	beyond 10 January, 2018, pending outcome of Board hearing.
Wednesday, January 10, 2018	Received email from contractor Shawn Wolfe with new NOA showing revised fastner spacing for metal panels. After review of NOA, current installa
January 10,2018	
·	