

Repair Estimate Station 5

MWI Pumps 7775 SW 9th. Street (Oslo Road) Vero Beach, FL 32968 Phone: (772) 770-0004 Fax: (772) 770-1096	Date: 11-16-20 Quote No: 20-0073 Customer P0#
--	--

Project: Quote To: Delivery:	Station 5 FPI#RH0706 or (RG2506) Terry Narrow- Operation Supervisor 516-312-5950 Village of Wellington, 14001 Pierson Rd. Wellington, FL 33414 Approximate turn around 60 days from order	Terms: Net 30 After Completion FOB: Jobsite Pierson Road Approved By: Quoted By: Bill Miller 954-682-2062
---	--	--

Item	Qty.	Description	Unit Price	Total Price
A	1	Furnish field transportation and shop labor to perform the following services for 18" FPI Vertical <ul style="list-style-type: none"> • Transport to and from jobsite • Disassemble and inspect pump • Replace top bearings, lower bearing and all seals • Check angles and balance impeller • Sandblast and epoxy paint pump and can • Replace belts • Reassemble pump and provide new lubricant • Check motor and mount <p>NOTE: Any items that are found that require repair/replacement not listed above, will be quoted and approved by the customer prior to work being completed. This unit was serviced in 2012.</p> <p>Customer is responsible for removing & reinstalling pump.</p>	\$11,774.00	\$11,774.00

WE LOOK FORWARD TO YOUR FAVORABLE CONSIDERATION
Please note that prices do not include applicable Sales Tax, Fees, Installation or Freight unless otherwise noted